






- | | | | |
|-----------|------------------------------------|-----------|--------------------------------|
| D | Montageanleitung | GB | Assembly instructions |
| FR | Notice de montage | IT | Istruzioni di montaggio |
| NL | Handleiding voor de montage | PL | Instrukcja montażu |
| CZ | Montážní návod | SK | Návod na montáž |
| HU | Szerelési útmutató | RO | Instrukțiuni de montaj |
| TR | Montaj talimatı | RU | Инструкция по монтажу |



0
10
20
30
40
50
60
70
80
90
100
110
120
130
140
150
160

A 030094
5x34 x12

B 030110
x12

C 230010
8x32 x12

D 070047
x2

E 070017
30x30 x4

F 240075
x2

Ga x1

Gb x1

Gc x1

Gd 3x15 x4

Ge x1

Gf x2

H 030053
M4x25 x4

J 210113
x4

K 250012
3,5x15 x8

L 250016
3,5x20 x4

M 180060
x2

N 180031
x2


O 240077
584 x1

P 090004
8x40 x2

Q 180080
x2

R 250012
3,5x15 x2

S 250044
4x40 x2





3

B








030110










x8



4



5






5

D 070047 x2

K 250012 3,5x15 x4

M 180060 x2



6

Ga x1

Gb x1

Gc x1

Gd 3x15 x4

Ge x1

Gf x2

